


### SOLITHERM PELTIER TG 3039 dehumidifier Installation guide

#### **Different mounting options**



- 1. Recessed mounting.
- 2. DIN Rail mounting.
- 3. Floor mounting.
- 4. Wall mounting (with optional frame)

#### **Technical Data**

Cooling Rate (30°C / 80%rH) 25 ml/hr Operating Temperature Range 0°C - 65°C

Mounting Recessed, DIN rail, enclosure floor Wall mount with mounting frame

Dimensions A  $\times$  B  $\times$  C (D+E) 176  $\times$  136  $\times$  (72+61) mm

A = Height | B = Width | C = Depth
Weight 1.8 kg

Cut out dimensions 152 x 117.5 mm

Voltage / Frequency
Rated current
2.1 A
Starting current
3.1 A
Max. current
2.4 A
Power consumption
50 W
Max. power
Fuse
4 A (T)

Connection Connection terminal block


Housing material PC UL94V-0


Approvals CE


Accessories Mounting Frame. Order Number 1019305





# 1. Recessed mounting installation and dimensions












#### Installation


The unit must be mounted to the wall of the enclosure using the provided (x4) 5x18 mm self-tapping screws for plastic:

TIGHTENING TORQUE: 0.8 Nm




### 2. <u>DIN Rail mounting installation and dimensions</u>






Step 1: Remove the 2 blanks using a screwdriver.




Removal

Mounting can be facilitated by pushing the clip downwards and inwards using a screwdriver.

To remove the bracket from the DIN rail use a screwdriver to push the clip downwards and outwards




Step 3: Position the unit inside the brackets and secure each side using the provided (x2) 5x18 mm self-tapping screws for plastic. Stop screwing as soon as the screw head is seated in place. **DO NOT OVERTIGHTEN!** 





Step 1: Unscrew the (x2) 5x18 mm screws from each side and remove the unit from the brackets. Step 2: Remove the brackets from the DIN rail by pressing with a screwdriver as shown in Step 2.





# 3. Floor mounting installation and dimensions


















## 4. Wall mounting (with optional frame)














- Step 1 After ensuring that both the recess and flush mount gaskets are assembled, mount the duct (1019305) to the unit (3039303) using the provided (x4) 5x18 mm self-tapping screws for plastic.

  TIGHTENING TORQUE: 0.8 Nm
- Step 2 Mount the unit to the wall of the enclosure using (x4) M4 screws.

  TIGHTENING TORQUE: 1.5 Nm



# Mounting Instructions

Read this instruction sheet before installing the unit. Only specialized personnel are allowed to install, maintain and clean the unit.

Ensure that for the duration of the installation, maintenance and cleaning the unit is disconnected from the electrical supply.

#### **Electrical Connection**

Check the type plate before making any connections to the power supply to ensure that current and voltage ratings are met.